

Exposure-Mat

The No Battery Exposure Meter

expomat.tripod.com

© 2003 INFORMATIQUES

1

Assembly Instructions

- 1 Print on 140 gsm card stock.
- 2 Lightly score fold lines A & B in 1.
- 3 Cut out centre rectangle from 1 using a craft knife and ruler.
- 4 Cut out 1 using craft knife and ruler.
- 5 Carefully fold 1 at A and B.
- 6 Cut out 2 using craft knife and ruler.
- 7 Assemble by sliding 2 into 1, check fit and adjust by trimming bottom edge of 2 if necessary.
- 8 Sparingly apply glue to marked section of 1, fold and leave to dry.
- 9 When dry slide 2 into 1 and follow use instructions.

Score

A


Score

B


2

Use Instructions

- 1 Align film speed with Exposure Value at top of window.
- 2 Read possible Aperture / Shutter Speed combinations at bottom of window.
- 3 For more information -
 "The Ultimate Exposure Meter"
www.fredparker.com
 "Who Needs A Light Meter Anyway?"
<http://www.pcisys.net/~rlnpjs/minolta/evlvasa.html>
 "Freebie Pocket Exposure Calculator"
rick_oleson.tripod.com
 and watch our site for updates
expomat.tripod.com



Cut Out This Rectangle



Exposure-Mat

Apply Glue Here

